

Comunicat AR - VideoCube 20210405

În weekendul 05.12.2020, acoperișul de la Arena Nationala a fost închis de către operatorii numiți de proprietarul Arenei Nationale. Operarea s-a efectuat contrar restructurărilor de anotimp, condiții meteorologice impuse de către producător. La operațiunea de deschidere, pe data de 07.12.2020, s-au rupt cablurile de la acoperiș, astfel blocând acoperișul în poziția intermediară.

AUROCON Romania a fost anunțată de problemele de la acoperiș în data de 10.12.2020. Pe data de 11.12.2020, o delegație a AUROCON s-a deplasat la Arena Nationala, constatând că acoperișul este în pericol de prăbușire din cauza acumulărilor foarte mari de apă.

Din data de 11.12.2020 până în data de 23.12.2020, AUROCON a efectuat lucrări de evacuare a apei de pe acoperiș, lucrări de fixare, reparații și parcare a acoperișului în poziția de mijloc – deschis. Operațiunile s-au efectuat după discuții verbale și acordului de execuție, scris din partea PMB.

De atunci până astăzi PMB nu a reușit să finalizeze procedurile pentru plata lucrărilor efectuate. Mai mult, pe data de 14.02.2021 PMB a anunțat că nu intenționează să finalizeze procedurile pentru plata sau pentru un contract direct.

De la începutul lunii Martie 2021, AUROCON Romania a fost abordată de diferite instituții (PMB, CMTIB, Comitetul de Organizare EM 2021, UEFA, FCSB București etc.) în vederea solicitării de acordare ajutor pentru operarea videocubului de la Arena Nationala.

AUROCON a refuzat orice intervenție pentru operare în Arena Nationala, din cauza lipsei bazei legale, adică acordul cu proprietarul acoperișului.

Mentionăm că AUROCON nu are responsabilități față de Arena Nationala, nu a avut și nici nu are un contract de mentenanță. Din contra a menționat cu repetate ocazii problemele tehnice care pun în pericol operarea în siguranță a acoperișului.

AUROCON Romania SRL

05.04.2021

Walter Hämmerle

Communique - VideoCube 20210405

During the weekend of 05.12.2020, the roof of the National Arena was closed by the operators appointed by the owner of the National Arena. The operation was carried out contrary to the seasonal and meteorological restrictions imposed by the manufacturer. During the opening operation, on 07.12.2020, several cables from the roof were broken, thus blocking the roof in the intermediate position.

AUROCON Romania was informed about of the problems on 10.12.2020. On 11.12.2020, a team from AUROCON went to the National Arena, finding that the roof is in danger of collapsing due to very large accumulations of water.

From 11.12.2020 to 23.12.2020, AUROCON performed works such as evacuation of water from the roof, fixing the roof in safe position, repairing and parking the roof in the middle - open position. The operations were carried out after verbal discussions and after written instruction to start with executions of the works sent by PMB.

From then until today, PMB has not been able to complete the procedures for payment for works performed. Moreover, on 14.02.2021 PMB announced that it is not intended to complete the procedures for payment or for a direct contract.

Since the beginning of March 2021, AUROCON has been approached by various institutions (PMB, CMTIB, Organizing Committee for EM 2021, UEFA, FCSB Bucharest etc.) in order to request assistance for the operation of the video cube from the National Arena.

AUROCON is not able to perform any intervention for operation in the National Arena, due to the lack of legal basis, such as an agreement with the owner of the roof.

We mention that AUROCON has no responsibilities in relation with the National Arena, did not have and does not have a maintenance contract. On the contrary, AUROCON Romania repeatedly mentioned the technical problems that endanger the safe operation of the roof.

AUROCON Romania SRL

05.04.2021

Walter Hämmerle